



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

Report Date: September 18, 2006

Supervisor

[Signature]

Mine Name: Mammoth Ridge
Operator Name: Burningham Enterprises
Gary Burningham
95 North 200 East
P.O. Box 974
American Fork, Utah 84003

Permit number: S/-17/048
Inspection Date: September 11, 2006
Time: 3:00 PM

Inspector(s): Doug Jensen
Other Participants: None
Mine Status: Inactive

Weather: Clear, warm

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:
Inspected the site while in the area.

Directions to Site:
Refer to previous inspection memo

Inspection Summary:
The site remains unchanged since the last inspection on August 2, 2005.

Conclusions and Recommendations:
I will continue to monitor the site while in the area.

Inspector's Signature *[Signature]*

Date: 9/18/06

dj:pb

cc: Burningham Enterprises
John Blake, SITLA ML-50071-OBA

Attachment: Map & Photos

O:\M017-Garfield\S0170048-MammothRidge\inspections\09112006insp.doc